

20 juillet 2006

00 :03	VAD1M	20	0-1	0	OK	Amas entre 30 km O et 180 km E
00 :09	VAD2M	20	1	0	OK	
00 :16	VAD1M	20	1	0	OK	
00 :22	VAD2M	20	1	0	OK	
00 :30	VAD1M	20	1	0	!	pulse a changé
00 :36	VAD2M	20	0	0		émetteur coupé entre les 2 séquences
Entre le VADS de 23 :49 et le VAD1M de 00 :30, le pulse est sur 200 km. Attention à l'interprétation : VAD1/2M+ alarme ON						
00 :43	VAD1M	20	0	0	OK	
00 :49	VAD2M	20	0	0	OK	
00 :55	VAD1M	20	0	0	OK	
01 :01	VAD2M	20	0	0	OK	
01 :08	VAD1M	20	0	0	OK	
01 :23	VAD2M	20	0	0	OK	
01 :43	VAD1M	20	0	0	OK	
01 :49	VAD2M	20	0	0	OK	
01 :56	VADS	20	0	0	OK	
02 :00	VAD1	19	0	1	OK	Bipolar
02 :05	VAD2	19	0	1	OK	Bipolar
02 :14	VAD1	19	1	1		Bipolar Planté au site 6,68
02 :20	VADS	20,5	0	0	OK	
02 :32	VADS	20,2	0	0	OK	
02 :46	VADS	20,2	0	0	OK	
02 :58	VADS	20,2	0	0	OK	
03 :12	VADS	20,2	0	0	OK	
03 :32	VADS	20,2	0	0	OK	
03 :35	VAD1M	20	0	0	OK	
03 :41	VAD2M	20	0	0	OK	
03 :48	VADS	20	0	0	OK	
04 :05	VADS	20,2	0	0	OK	
04 :13	VAD1	20,2	0	1	OK	Bipolar
04 :20	VAD2	19,5	0	1	OK	Bipolar
04 :26	VAD1	19,5	0	1		Plantage PC. Reboot
04 :35	VADS	20,2	0	0	OK	
04 :39	VAD1M	20	0	0	OK	
04 :45	VAD2M	20	0	0	OK	
05 :05	VADS	20,2	0	0	OK	
05 :10	VAD1M	20	0	0	OK	
05 :17	VAD2M	20	0	0	OK	
05 :25	VADS	20	0	0	OK	
05 :30	VADS	20	0	0	OK	
05 :45	VADS	20,5	0	0	OK	
06 :00	VADS	20,5	0	0	OK	
06 :34	VADS	20,5	0	0	OK	
06 :48	VADS	20,5	0	0	OK	
07 :02	VADS	20,5	0	0	OK	
07 :15	VADS	20	0	0	OK	
07 :32	VADS	20	0	0	OK	Pb IA dans zone météo site 2°

07 :36	VADS	20,5	0	0	OK
07 :50	VADS	20,5	0	0	OK
08 :09	VADS	20,5	0	0	OK
08 :23	VADS	20,5	0	0	OK
08 :28	VAD1	22-20	0	1	OK
08 :34	VAD2	20	0	1	planté à site 3,6°
08 :43	VADS	20	0	0	OK
08 :47	VAD1	20-18	0-1	1	OK
08 :54	VAD2	19	1	1	OK
09 :00	VAD1	19-20	1	1	OK
09 :07	VAD2	19	1	1	OK
09 :13	VAD1	20	1	1	OK
09 :20	VAD2	20	1	1	OK
09 :27	VAD1	20	1	1	OK
09 :33	VAD2	20-19,5	1	1	OK
09 :40	VAD1	20	1	1	Pb IA dans la zone météo
09 :47	VADS	20	0	0	OK
09 :51	VAD1	20-19	0-1	1	OK
09 :57	VAD2	19	1	1	OK
10 :07	VADS	20	0	0	OK
10 :12	VAD1	20-19	0-1	1	OK:LED bipolar clignote, s'éteint et se rallume
10 :18	VAD2	19	1	1	OK
10 :25	VAD1	19-20	1	1	Pb CAF rétabli manuellement mais l'émetteur ne démarre pas. Plantage PC, magnétron à 0. Après ce pb, pluie intense sur Ronsard.
12 :47	VADS	14	0	0	OK
12 :53	VAD1	12	0	0-1	OK Très beau cas de pluie stratiforme
13 :00	VAD2	12	0	1	Grosses gouttes
13 :07	VAD1	12	0	1	
13 :14	VAD2	12	0	1	
13 :25	VAD1	16-14	0	1	pb butée site
13 :37	VADS	18	0	0	OK
13 :40	VAD1	16,5	0	1	OK
13 :47	VAD2	16	0	1	OK
13 :52	VAD1	16	0	1	OK
14 :00	VAD2	16	0	1	OK
14 :07	VADS	18	0	0	
14 :11	VAD1	17	0	1	PC planté à 5,54° site
14 :19	VAD1	20-17	0	1	OK
14 :26	VAD2	18-16	0	1	OK
14 :32	VAD1	16	0	1	arrêt émetteur pour ravitaillement
14 :41	VAD1	18-16	0	1	OK
14 :48	VAD2	16	0	1	OK
14 :54	VAD1	16	0	1	Butée gisement
15 :07	VADS	18	0	0	OK
15 :11	VAD1	17-16	0-1	1	Bruit apparent malgré magnétron et CAF
15 :17	VAD2	16	1	1	OK Planté à 12° site

15 :26	VAD1	19	0	1	Planté à 0,26°
15 :30	VAD1	17	0	1	OK
15 :37	VAD2	16	0-1	1	OK
15 :53	VADS	18	0	0	OK
16 :00	VAD1	18	0	1	Planté butée gisement
16 :08	VAD1	18-16	0	1	OK
16 :16	VAD2	16	0	1	OK LED alarme clignote puis s'allume
16 :23	VADS	16	0	0	OK
16 :27	VAD1	16	0	1	Planté butée gisement
16 :36	VAD1	18-16	1	1	OK
16 :42	VAD2	16	1	1	OK
16 :49	VAD1	16	1	1	OK
16 :55	VAD2	16	1	1	OK
17 :02	VAD1	16	1	1	Planté butée gisement
17 :11	VAD1	19-16	1	1	OK
17 :17	VAD2	16	1	1	OK
17 :24	VADS	18	0	0	OK
17 :39	VADS	18	0	0	OK
17 :54	VADS	18	0	0	OK